

CHICCO OASYS I-SIZE CAR SEAT – VOLUNTARY REPLACEMENT PROGRAM



Chicco is announcing a voluntary replacement program involving Oasys i-Size child restraint system, distributed between 27 September 2018 and 4 April 2019.

The product (Oasys i-Size, code 79598 and code 79133) can be easily identified through the label (A) placed under the seat, showing homologation number (B) 000016 and the serial number (C).

Only Chicco Oasys i-Size car seat units with serial number from 00008139 to 00013590 and equipped with the highlighted buckle model (see picture) are involved.

Chicco Oasys 0+, and Chicco Oasys i-Size equipped with different harness buckles, are not involved in this voluntary replacement program.

During a specific dynamic test conducted at ADAC with ICRT International Consumer Research Organisation, the breakage of a component of the harness system was observed.

The test has been performed with speed and loads exceeding safety requirements established by European Regulation.

Chicco Oasys i-Size complies with the strictest and most recent applicable European safety regulation (UN ECE R129, known as i-Size regulation) and, therefore, assures a high level of safety and can be used for safe transportation of babies.

Chicco, always committed to meet and exceed the highest quality standards and customer expectations, is inviting the users of the product to contact local Customer Service (Contacts: <https://www.chicco.com/en/contact.html>) to receive a free of charge replacement spare part that will further enhance the product safety performance.

We apologise for any inconvenience caused by this replacement program.

