


Safety Alert

Hemco Anchor Bracket Supplied With KeyFit Plus Infant Car Seat



Hemco Tether Anchor
Bracket Assembly

Faulty Bracket
Batch No. Shown Here

The Product : Hemco Tether Anchor Bracket supplied with Chicco KeyFit Plus Car Seat

The Defect : Batch No. 022 & 023 of the Hemco tether anchor brackets are faulty. This anchor bracket connects the car seat tether strap to the car anchorage bolt.

The Hazard : If the tether anchor bracket fails in the event of a collision, the performance of the car restraint may be impacted increasing the risk of injury.

What should consumers do? :

Anyone using the Hemco tether anchor bracket should :

1. Check the batch number stamped on it. The faulty batch numbers are : 022 & 023
2. If '022/023', cease using the car seat immediately & replace **only** anchor bracket.
3. The car seat is not directly involved in the recall and does not need to be returned or replaced. Only the tether anchor bracket needs to be changed.
4. Contact Chicco by email info@chicco.com.au or phone +612 8543 5570

Request a Hemco tether anchor bracket and Chicco will immediately send you a **free** replacement.

Please ensure that you supply full address & contact details.



wherever there's a baby